



JON M. HUNTSMAN, JR.  
Governor

GARY R. HERBERT  
Lieutenant Governor

**State of Utah**  
**DEPARTMENT OF NATURAL RESOURCES**  
**Division of Oil, Gas & Mining**

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

**Inspection Report**  
**Minerals Regulatory Program**  
Report Date: September 29, 2006

Supervisor *[Signature]*

**Mine Name:** Dry Creek mine  
**Operator Name:** All Gypsum Corporation  
Jim Fain  
4388 North Bulldog Road  
Cedar City, Utah 84720

**Permit number:** S/021/026  
**Date:** September 15, 2006  
**Time:** 8:00 AM

**Inspector(s):** Doug Jensen  
**Other Participants:** None  
**Mine Status:** Inactive

**Weather:** Cool, Windy

| Elements of Inspection   | Evaluated                | Comment                  | Enforcement              |
|--|--------------------------|--------------------------|--------------------------|
| 1. Permits, Revisions, Transfer, Bonds   | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Public Safety (shafts, adits, trash, signs, highwalls)                      | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Protection of Drainages / Erosion Control                                   | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 4. Deleterious Material  | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 5. Roads (maintenance, surfacing, dust control, safety)                        | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 6. Concurrent Reclamation  | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes) | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 8. Water Impoundments  | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 9. Soils   | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 10. Revegetation   | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 11. Air Quality  | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 12. Other  | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

**Purpose of Inspection:**

Inspected the site while I was in the area.

**Directions to Site:**

See previous inspection report.

**Inspection Summary:**

The site is unchanged since my last site inspection on October 27, 2005. I photographed and GPSd the area during my last visit so I did not further document the site.

**Conclusions and Recommendations:**

I will continue to monitor the site when I am in the area.

**Inspector's Signature**

*[Signature: Doug Jensen]*

**Date:**

9/29/06

dj:pb

cc: All gypsum Corporation

O:\M021-Iron\S0210026-DryCreekMine\inspections\09152006insp.doc